

Sierra Industries, Ltd.
122 Howard Langford Drive
Uvalde, Texas 78801

AFMS Temporary Change
FAA STCs SA3634SW & SA3853SW

TEMPORARY FAA APPROVED AIRPLANE FLIGHT MANUAL SUPPLEMENT CHANGE

Temporary Change No. 1 dated October 12, 2010

Publication Affected: Cessna U206A, B, C, D, E, F and G; P206A, B, C, D and E; 206H and T206H; and 207 Series Aircraft FAA Approved Airplane Flight Manual Supplements for STCs SA3634SW and SA3853SW (Sierra Industries, Ltd. Long Range Fuel System):

AFMS Documents Affected:

SI10680, SI10681, SI10682, SI10683, SI10684, SI10685, SI10688, SI10689, SI10690, SI10691 and SI10692

Airplane Serial Numbers Affected: All Cessna 206 and 207 aircraft modified by STCs SA3634SW and SA3853SW.

Description of Change: Section 4, Normal Procedures

Filing Instructions: Insert this temporary change into the FAA Approved Airplane Flight Manual Supplement.

Removal Instructions: Upon receipt of a revised AFMS.

In Section 4, Normal Procedures:

TEMPORARY OPERATING NOTICE (FUELING OPERATIONS)

1. When fueling your aircraft ensure that enough time (at least 5 minutes) is allowed for the fuel to completely transfer through all of the auxiliary fuel bladders into the main tank before checking the fuel level.

APPROVED:


M. Monica Merritt
Airplane Certification Office
Federal Aviation Administration
Fort Worth, TX 76137

DATE:

11/19/10